

Inspection Photos

01/17/2025

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 416774

Inspection Doc: 718100195

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 416774




Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 416774



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 416774



Photo 3: Pipe/Lines on the east end of the separator equipment are open/exposed.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 416774



Photo 4: Photos taken from the east end of the Location. Photo shows areas of the Location where vegetation establishment is not uniform; soils are predominantly bare. Additional reclamation efforts required within these areas.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 416774



January 17, 2025

Photo 5: Photo taken from the southeast end of the Location, facing east. Photo shows trailer/trash debris remains improperly stored on the Location. This is interfering with the reclamation and Operator's ability to achieve uniform vegetative establishment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources