

**Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575**



Debris



Debris

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Staining below combustor



Staining around wellhead

**Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575**



Staining from engine leaks



Staining from engine leaks

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Unlabeled chemical tank



Unlabeled chemical tank

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575

Jan 23, 2025 at 10:28:59 AM



Unlabeled tank

Jan 23, 2025 at 10:29:28 AM



Unlabeled tank

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Staining around chemical tank



Staining around chemical tank

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Staining around treater



Staining around treater

**Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575**



Oily waste and staining at treater



Stained material throughout tank battery

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Stained material throughout tank battery



Stained material throughout tank battery

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Oily waste and staining



Oily waste and staining

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Debris



Soil staining at truck load out

**Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575**



Oily waste inside unidentified drilling pit



Oily waste inside unidentified drilling pit

Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575



Location from Northeast entrance



Location from Northwest corner

**Robert L Bayless Producer LLC
Weaver Ridge 14 Well Pad
Location ID: 465575**



Location from Southwest corner



Location from Southeast corner