

**State of Colorado
Energy & Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404061154

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: NOBLE ENERGY INC	Operator No: 100322	Phone Numbers
Address: 1099 18TH STREET SUITE 1500		Phone: (303) 597-6847
City: DENVER	State: CO	Zip: 80202
Contact Person: Phillip Porter	Email: RBUEUF27@chevron.com	Mobile: ()

PROJECT, PURPOSE & SITE INFORMATION**PROJECT INFORMATION**

Remediation Project #: 30294 Initial Form 27 Document #: 403420243

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☒ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: WELL	Facility ID: _____	API #: 123-38670	County Name: WELD
Facility Name: Wells Ranch AA35-62-1AHNC	Latitude: 40.437499	Longitude: -104.394114	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWSW	Sec: 36	Twp: 6N	Range: 63W
Meridian: 6	Sensitive Area? Yes		

SITE CONDITIONS

General soil type - USCS Classifications CL

Most Sensitive Adjacent Land Use Grassland

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

NA

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☒ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	NA	Not encountered
Yes	SOILS	100' x 100' x 12.5'	Lab analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Pursuant to ECMC Rule 911 a site investigation was conducted pertaining to the WELLS RANCH AA35-62-1AHNC wellhead cut and cap and flowline abandonment. The wellhead was cut and capped per ECMC rules. Approximately 2017' of flowline was abandoned-in-place as per doc #403778105. This flowline lies in a common trench with at least one other line. So as to not disturb the other line(s) sharing the common trench, soil samples were only be taken at the wellhead and at the endpoint of the flowline. The ECMC will be updated in a supplemental Form 27 if a portion of the flowline is able to be removed.

Five (5) grab soil samples were collected from the subsurface on the N-E-S-W sides of the wellhead outside of the casing collar (4), and from pea gravel/loose material at the based of the excavation inside of the casing collar. Additionally, soil samples were field screened at the N-E-S-W sides of the wellhead. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, EC, SAR, pH metals, and boron. All samples collected were/will be analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☐ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 46

Number of soil samples exceeding 915-1 9

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 1000

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

NA / ND

-- Highest concentration of TPH (mg/kg) 73.79

-- Highest concentration of SAR 1.6

BTEX > 915-1 Yes

Vertical Extent > 915-1 (in feet) 4

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION☐ Were impacts to adjacent property or offsite impacts identified?☐ Were background samples collected as part of this site investigation?☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Operator is conducting a thorough review of the Site.

If not already completed, soil samples will be collected at the start/end points of the flowline. Soil samples will be analyzed by a certified laboratory for the full extent of Table 915-1, EC, SAR, pH, metals, and boron.

A background sample was collected from native, off-pad soil near the wellhead for EC, SAR, pH, boron, and ECMC Table 915-1 metals analysis. Residual inorganics and metals (except arsenic and barium) at the site appear less than and/or consistent with background comparison. Additional backgrounds (10) were previously collected from native soil of similar lithologic material and intervals to further compare residual arsenic and barium.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No current source was generated. A site assessment was completed to delineate soil impacts at the former wellhead, with samples collected for analysis of TPH C6-36, ECMC Table 915-1 organics, arsenic, and barium. Additional backgrounds (27) were collected from native soil of similar lithologic material and intervals to further compare residual arsenic and barium.

The absence of groundwater and the local lithology suggest that a pathway to groundwater at this location is unlikely, therefore, Operator proposes to use ECMC Table 915-1 Residential Soil Screening Levels (RSSLs) at this site.

All organic, inorganic (except pH) and metal concentrations are in compliance with ECMC Table 915-1 RSSLs and/or local background levels and do not appear to warrant additional assessment. Elevated pH levels are consistent with background samples taken during the flowline assessment.

REMEDATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Results of the subsurface assessment indicate that residual petroleum hydrocarbon impacts have been vertically and laterally defined. Operator proposes to use ECMC Table 915-1 RSSLs at this site. All concentrations at the site are in compliance with ECMC Table 915-1 RSSLs and/or local background comparison.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during the subsurface assessment.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other

☐ **Request Alternative Reporting Schedule:**

☐ Semi-Annually ☐ Annually ☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other Quarterly Update

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Operator has general liability insurance (policy MWZZ 316714) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website.

Operator anticipates the remaining cost for this project to be: \$ 10000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

--

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 01/03/2024

Proposed date of completion of Reclamation. 10/31/2029

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 05/16/2023

Actual Spill or Release date, or date of discovery. 01/16/2024

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/03/2024

Proposed site investigation commencement. 07/01/2023

Proposed completion of site investigation. 08/29/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 01/03/2024

Proposed date of completion of Remediation. 08/06/2024

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☒ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

Operator is conducting a thorough review of the Site. While the wellhead soil appear to be delineated, confirmation of flowline sampling and compliance needs to be confirmed. The Implementation scheduled is being updated to account for site review and additional site investigation activities, if required.

OPERATOR COMMENT

This form serves as a quarterly update.

Per the previous form (#403960160) was submitted on 10/27/2024 and has been denied due to data validation. Operator is performing a robust project review and is requesting a validated data package from the laboratory for submittal when received.

If not already completed, soil samples will be collected to ensure flowline sampling closure compliance.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: William Schoff

Title: Environmental Consultant

Submit Date: _____

Email: cvxform27@erm.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____

Date: _____

Remediation Project Number: 30294

COA Type**Description**

0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

--	--

Total Attach: 0 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)