



Inspection Photos
Location Name: FEDERAL-18-16
Location ID: 322406
Inspection Date: 1/22/2025

Federal 18-16 Location.

Jan 22, 2025 11:27:50 AM
+39.4462N -109.0213W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FEDERAL-18-16
Location ID: 322406
Inspection Date: 1/22/2025

Wellhead P&A marker.

Jan 22, 2025 11:24:40 AM
+39.4462N -109.0213W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FEDERAL-18-16
Location ID: 322406
Inspection Date: 1/22/2025

Wellhead P&A marker.

Jan 22, 2025 11:25:30 AM
+39.4462N -109.0213W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FEDERAL-18-16

Location ID: 322406

Inspection Date: 1/22/2025

Excavated and
decommissioned
flowline(s).

Jan 22, 2025 11:25:14 AM
+39.4462N -109.0213W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FEDERAL-18-16
Location ID: 322406
Inspection Date: 1/22/2025

Excavated and
decommissioned
flowline(s).

Jan 22, 2025 11:26:36 AM
+39.4461N -109.0217W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FEDERAL-18-16

Location ID: 322406

Inspection Date: 1/22/2025

Apparent excavated pit
on the southwest corner
of the location.

Jan 22, 2025 11:26:24 AM
+39.4460N -109.0217W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FEDERAL-18-16

Location ID: 322406

Inspection Date: 1/22/2025

Apparent excavated pit
on the southwest corner
of the location.

Jan 22, 2025 11:26:10 AM
+39.4460N -109.0215W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FEDERAL-18-16

Location ID: 322406

Inspection Date: 1/22/2025

Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105.

Jan 22, 2025 11:26:49 AM
+39.4460N -109.0217W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: FEDERAL-18-16
Location ID: 322406
Inspection Date: 1/22/2025

Trash and waste.

Jan 22, 2025 11:24:25 AM
+39.4462N -109.0212W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: FEDERAL-18-16

Location ID: 322406

Inspection Date: 1/22/2025

Trash and waste.

Jan 22, 2025 11:24:48 AM
+39.4462N -109.0213W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources