

# Inspection Photos

Loc: 308104

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/24/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing north toward the location.



Inspection Photos



**Photo 2.** Facing toward the PW pit which has sufficient freeboard.



## Inspection Photos



**Photo 3.** The well sign is posted on the meter shed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308104 | Date: 1/24/2025