

Inspection Photos

Loc: 308105

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/24/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308105 | Date: 1/24/2025

Inspection Photos



Photo 2. There was a water leak at the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308105 | Date: 1/24/2025

Inspection Photos



Photo 3. Facing toward the PW pit which has sufficient freeboard..

