

Inspection Photos

Location: Antelope Sec. 19 Compressor Station

Location ID: 487890

API #




Photo 1 –Well placard



Photo 2 – Tanks Facilities



Inspection Photos
Location: Antelope Sec. 19 Compressor Station/
Location ID: 487890
API #



Photo 3 – Heater treater



Photo 4 – Compressor Cooling Unites

Inspection Photos
Location: Antelope Sec. 19 Compressor Station
Location ID: 487890
API #



Photo 3 – Hydrocarbon spot



Photo 4 – Hydrocarbon spot