

# Inspection Photos

Loc: 307693

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 1/24/2025

County: LAS ANIMAS




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307693 | Date: 1/24/2025

## Inspection Photos



**Photo 2.** There is rock rip/rap and a berm installed at the base of the cut slope.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307693 | Date: 1/24/2025



## Inspection Photos



**Photo 3.** Facing toward the fill slope which is stabilized with vegetation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307693 | Date: 1/24/2025