

Operator: Crestone Peak Resources

Location Name: Left Hand 3-65 13-0

Loc ID: 455750

Inspection: 7133901101



CA: One (1) meter shed remains at the location. Refer to the attached inspection photos. Comply with the reclamation rules to remove all debris, abandoned gathering line risers, flowline risers, and equipment (regardless of ownership) within three months of plugging (11/29/2023) the associated facility. All work should have been conducted by 2/29/2024.

CA Resolution: Operator has reported that midstream shack has been removed, as well as additional debris and equipment to comply with reclamation rules.