

Inspection Photos

01/17/2025

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334923

Inspection Doc: 718100203

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334923



January 17, 2025



January 17, 2025

Photo 1: Photos 1-2 taken from the south end of the location. Photos provide an overview of the Location from west to northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334923



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334923



Photo 3: Photos 3-4 taken from the eastern and northern interim areas of the Location. Photos examples showing various equipment/vehicles, and other miscellaneous items being stored within the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334923



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources