

Inspection Photos

01/17/2025

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335006

Inspection Doc: 718100209

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335006



Photo 1: Photos 1-2 taken from the east end of the location. Photos provide an overview of the Location from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335006



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335006




Photo 3: Unused ladder equipment stored next to wells.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources