

Inspection Photos

Location Name: White Star Farms 4-23

API Number: 125-07497



1. Lease sign at well location.



2. View of wellhead. Well leaking at packing at time of inspection.

Inspection Photos
Location Name: White Star Farms 4-23
API Number: 125-07497




3. View of wellhead area.



4. Well location overview.

Inspection Photos
Location Name: White Star Farms 4-23
API Number: 125-07497



5. Lease sign at gathering location.



6. Gathering location overview.