



Approximate spill location (Spill ID: 488862). Excavation has been backfilled.




Approximate spill location (Spill ID: 488862). Excavation has been backfilled.






Approximate spill location (Spill ID: 488862). Excavation has been backfilled.



Approximate spill location (Spill ID: 488862). Excavation has been backfilled.





Wildlife observed.




Wildlife observed.





Salt crusting observed along flowline and throughout field.




Salt crusting observed along flowline and throughout field.






Salt crusting observed along flowline and throughout field.



Salt crusting observed along flowline and throughout field.





Approximate spill location (Spill ID: 488858). Excavation has been backfilled.

