



Orange construction fencing surrounds two areas.




Orange construction fencing surrounds two areas.





Animal scat observed adjacent to excavation.



Unnecessary equipment (battery) observed onsite.





Southwestern excavation area.



Southwestern excavation area.





Open excavation with snow accumulation and bird netting.



Open excavation with snow accumulation and bird netting.





Northeastern excavation area.




Northeastern excavation area.






s snow accumulation and partial



snow accumulation and partial





Wildlife tracks observed.

