

Excavation backfilled. Fencing surrounds former wellhead.





Ruts observed near former wellhead.



Small piles of soil observed near former wellhead.





Small piles of soil observed near former wellhead.



Wildlife tracks observed near former wellhead.





Excavation backfilled. Fencing surrounds former wellhead.

