


Signage with emergency contact phone number is visible at the tank battery.



Production tanks with NFPA placards are contained within a metal berm and secured by a metal fence.





Infrastructure is secured by metal fencing.



Utility flags are present on location.










Ancillary equipment within fencing.



Ruts observed on the west side of the location.

