

Final Reclamation and Stormwater Inspection

January 10, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320576

Well Name: CO STATE A #24-36

Inspection Document #: 718600183

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576



Photo 1. Photo taken looking east down access road from well Loc #319798. Access road and location appears to have reclamation activities performed with evidence of straw crimping. Undesirable annual plant species are present (Kochia and Russian thistle).




Photo 2. Looking east across well location. See Photo 1 comments.



Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576




Photo 3. Looking west from well location. See Photo 1 comments.




Photo 4. Looking north from well location. See Photo 1 comments.



Inspection Photos
Location Name: CO STATE A #24-36
Location ID: 320576




Photo 5. Looking east from well location. See Photo 1 comments.



Photo 6. Looking east from well location. See Photo 1 comments.

