

# Final Reclamation and Stormwater Inspection

January 10, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319795

Well Name: STATE A #3

Inspection Document #: 718600187

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 1.** Looking east along access road from well location ID #319795 toward well site. It appears that this section of access road is progressing towards 80% of reference area vegetation.



**Photo 2.** Overview of well location looking east across well site. Undesirable annual weedy species Kochia and Russian thistle dominate location.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 3.** Looking north from well location. See Photo 2 comments.



**Photo 4.** Looking south from well location. See Photo 2 comments.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795




**Photo 5.** Looking north from east side of location towards northern access road. List B noxious weeds Bull thistle and Scotch thistle are present on location.



**Photo 6.** Looking west along north access road from well location. Kochia and Russian thistle are dominant along access road.



Inspection Photos  
Location Name: STATE A #3  
Location ID: 319795



**Photo 7.** Aerial Photo from google 09/2023. All wells being serviced by main access road are plugged and abandoned. Vegetation has not established on access road. Main access road appears to require further reclamation (red circle). Also pictured, north access road (blue circle), Well location (green circle), western access road (yellow square).

