

# Final Reclamation and Stormwater Inspection

January 10, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319805

Well Name: STATE A #6

Inspection Document #: 718600191

Adams County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STATE A #6  
Location ID: 319805



**Photo 1.** Looking east along access road near well location. Undesirable annual weedy species Kochia and Russian thistle are present on the access road.



**Photo 2.** Overview of well location looking northeast across well site. Bare patches of soil are present on access road. Undesirable annual weedy species Kochia and Russian thistle are present throughout the site. List B noxious weed Scotch thistle is also present on location. It appears desirable perennial species are beginning to establish on location.



Inspection Photos  
Location Name: STATE A #6  
Location ID: 319805



**Photo 3.** Looking north from well location. See Photo 2 comments.



**Photo 4.** Looking west from well location. See Photo 2 comments.



Inspection Photos  
Location Name: STATE A #6  
Location ID: 319805



**Photo 5.** Looking south from well location. See Photo 2 comments.



**Photo 6.** Looking east from well location. See Photo 2 comments.

Inspection Photos  
Location Name: STATE A #6  
Location ID: 319805



**Photo 7.** Trash (bucket) is present on site near the center of the location.



**Photo 8.** Picture taken from northeast side of location looking south. List B noxious weed Scotch thistle is present on location.



Inspection Photos  
Location Name: STATE A #6  
Location ID: 319805



**Photo 9.** Aerial Photo from google 09/2023. All wells being serviced by main access road are plugged and abandoned. Vegetation has not established on access road. Main access road appears to require further reclamation (red circle).

