

Final Reclamation and Stormwater Inspection

January 10, 2025

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320548

Well Name: CO STATE A #33-36

Inspection Document #: 718600193

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CO STATE A #33-36

Location ID: 320548



Photo 1. Looking northwest along access road from road junction. Undesirable annual weedy species Kochia and Russian thistle are dominant on the access road.



Photo 2. Overview of well location looking northwest across well site. Undesirable annual weedy species Kochia and Russian thistle are dominant throughout the site.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Number: 718600193

Inspection Photos
Location Name: CO STATE A #33-36
Location ID: 320548



Photo 3. Looking north from well location. See Photo 2 comments.



Photo 4. Looking south from well location. See Photo 2 comments.



Inspection Photos
Location Name: CO STATE A #33-36
Location ID: 320548




Photo 5. Looking east from well location. See Photo 2 comments.



Photo 6. Reference area. taken west of well location.



Inspection Photos
Location Name: CO STATE A #33-36
Location ID: 320548



Photo 7. Aerial Photo from google 09/2023. All wells being serviced by main access road are plugged and abandoned. Vegetation has not established on access road. Main access road appears to require further reclamation (red circle). Also pictured is wellsite (green circle).

