

# Inspection Photos

01/22/2025

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 334919

**Inspection Doc:** 718100215

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334919



**Photo 1:** Photos 1-2 taken from the southeast end of the working pad surface. Photos provide an overview of the Location from southwest, west, northwest to northeast.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334919



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334919



**Photo 3:** Photo example showing the interim areas of the Location. Limited inspection due to snow cover, however vegetation that was observable appears to be establishing towards 1003 standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334919



**Photo 4:** Photo shows holes/tears within the secondary containment liner

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334919



**Photo 5:** Photo shows holes/tears within the secondary containment liner; patch previously applied has separated from the liner.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334919



January 22, 2025

**Photo 6:** BMPs to stabilize the working pad surface, as well as to minimize vehicle tracking show signs of disrepair; tracking/ruts becoming evident. Maintenance advised.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources