

Inspection Photos

01/22/2025

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334952

Inspection Doc: 718100227

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334952



Photo 1: Photos taken from the southeast end of the working pad surface. Photos provide an overview of the Location from northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334952



Photo 2: Photos examples showing the interim areas of the Location..



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334952



Photo 3: Photo examples showing the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources