

Inspection Photos

Loc: 321579

Operator: CITATION OIL & GAS CORP

Inspection Date: 1/28/2025

County: CHEYENNE



Inspection Photos



Photo 1. Facing east at the location. There was a leak at the wellhead that had just occurred. The leak misted off the location which will require the spil to be reported and properly cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321579 | Date: 1/28/2025

Inspection Photos



Photo 2. Facing east at the wellhead. There was a leak at the wellhead that had just occurred. Workers that were at the site have spread sand over this area and were dragging out the stained soil.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321579 | Date: 1/28/2025

Inspection Photos



Photo 3. After pushing the sand away it was observed that there are saturated oil stained soils which must be properly cleaned up and removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321579 | Date: 1/28/2025

Inspection Photos



Photo 4. Facing east toward the misted spill that went off location. Part of this area was dragged which covered some of the stained soils.



Inspection Photos



Photo 5. Standing at the approximate end of the stained grass which was 375' from the wellhead.



Inspection Photos



Photo 6. Standing at the approximate end of the stained grass which was 375' from the wellhead.



Inspection Photos



Photo 7. Inside the engine shed. It appears the leak was repaired. There is fresh sand in this area and it is presumed that oily waste was cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321579 | Date: 1/28/2025