

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/36NENE

Location ID: 335848

Date: 1/27/2025



Location Entrance – Photo #06168



Location – Photo #06179

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/36NENE

Location ID: 335848

Date: 1/27/2025



Jan 27, 2025 at 14:09:12

Location – Photo #06180



Jan 27, 2025 at 14:05:57

Location – Photo #06175



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/36NENE

Location ID: 335848

Date: 1/27/2025



Location – Photo #06170



Location – Photo #06171



Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/36NENE

Location ID: 335848

Date: 1/27/2025



Flowline Maintenance – Photo #06177



Flowline Maintenance – Photo #06178

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/36NENE

Location ID: 335848

Date: 1/27/2025



Open-Ended Hose/Wildlife Entry Hazard – Photo #06173



Open-Ended Hose/Wildlife Entry Hazard – Photo #06174