

Inspection Photos

Loc: 476137

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 1/28/2025

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the tank battery,



Inspection Photos



January 28, 2025
+38.878457,-102.814770
Cheyenne County
ECMC

Photo 2. Facing northeast toward the tank battery. The oil stained waste remains around the tanks. Some of the tanks were removed since the previous inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 3. There are oil stained waste between the tanks from a previous spill.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 4. There is oil stained waste between the tanks from a previous spill.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 5. It appears there was a recent spill that occurred near the heater treater. The surface and equipment is blackened from a hydrocarbon mist that recently occurred.



Inspection Photos



Photo 6. East side of the tank battery facing west. It appears the leak flowed to the southeast corner of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 7. It appears there was also a condensate leak that flowed from the shed at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 8. Southeast corner of the location facing northwest toward the tank battery facility. It appears the leak had overtopped this corner with visible impacts shown by the shovel at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 9. There are signs of a leak at the top of the fiberglass tank.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 1/28/2025

Inspection Photos



Photo 10. It appears the fiberglass tank at the west side also leaked fluids.



Inspection Photos



Photo 11. There skid steer track which may have removed some of the impacts.



Photo 12. There is a pile of oily waste stored at the location to the northeast #476172.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources