

# Inspection Photos

January 24th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325665

Inspection Document #: 714001742

La Plata County, CO

Township: NENE 29 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Location Name: Beuten A1  
Location ID: 325665



Photo 1. View of the wellhead assembly.



Inspection Photos  
Location Name: Beuten A1  
Location ID: 325665

1/24/25  
243° SW



**Photo 2.** Separator label has deteriorated and is no longer legible.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06800



Inspection Photos  
Location Name: Beuten A1  
Location ID: 325665



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Unused oil and gas equipment observed in the western portion of the pad.

API #: 067-06800



Inspection Photos  
Location Name: Beuten A1  
Location ID: 325665

1/24/25  
337° NW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Eastern interim reclamation area composed of Sand Dropseed, Yellow Hoary Aster and Rabbitbrush.

API #: 067-06800



Inspection Photos  
Location Name: Beuten A1  
Location ID: 325665

1/24/25  
175° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Sagebrush, Juniper, Four Winged Saltbush, Crested Wheatgrass and Sand Dropseed.

API #: 067-06800