

Inspection Photos

January 24th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325624

Inspection Document #: 714001743

La Plata County, CO

Township: SESE 20 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Beuten B1
Location ID: 325624

1/24/25
284° W



Photo 1. View of the well pad from the access point facing center.

Inspection Photos
Location Name: Beuten B1
Location ID: 325624



Photo 2. Stained soils at oillift equipment.

Inspection Photos
Location Name: Beuten B1
Location ID: 325624

1/24/25
114° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Southern interim reclamation area composed of Rabbitbrush, Crested Wheatgrass and Sand Dropseed.

API #: 067-06725

Inspection Photos
Location Name: Beuten B1
Location ID: 325624

1/24/25
175° S

