

# Inspection Photos

January 24th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333562

Inspection Document #: 714001745

La Plata County, CO

Township: SNESW 20 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ute GU AA  
Location ID: 333562



1/24/25  
160° S



Photo 1. View of the well pad from the access point facing center.



Inspection Photos  
Location Name: Ute GU AA  
Location ID: 333562



**Photo 2.** View of wellhead assemblies, no stained soils were observed.



**Photo 3.** View of the northern and western interim reclamation areas composed of Sand Dropseed, James Galleta and Rubber Rabbitbrush.

Inspection Photos  
Location Name: Ute GU AA  
Location ID: 333562

1/24/25  
90° E

