

# Inspection Photos

January 24th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306807

Inspection Document #: 714001746

La Plata County, CO

Township: NENE 19 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Southern Ute Q2  
Location ID: 306807

1/24/25  
73° E



**Photo 1.** View of the well pad from the access point facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08806



1/24/25  
194° S





Inspection Photos  
Location Name: Southern Ute Q2  
Location ID: 306807





1/24/25  
87° E





1/24/25  
87° E

