

# Final Reclamation and Stormwater Inspection

Date: 01/28/2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 306751

Inspection Document #: 718700018

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos

Location Name: Callen - USX N-65N67W

Location ID: 306751



**Photo 1.** Facing south near the former meter shed location. It appears that all meter sheds have been removed from the location.

Inspection Photos

Location Name: Callen - USX N-65N67W

Location ID: 306751



**Photo 2.** Facing northwest near the former meter shed location. It appears that all meter sheds have been removed from the location.

Inspection Photos

Location Name: Callen - USX N-65N67W

Location ID: 306751




**Photo 3.** Facing northeast near the eastern tank battery entrance. Road base material and culvert remain.

Inspection Photos  
Location Name: Callen - USX N-65N67W  
Location ID: 306751



**Photo 4.** Facing north near the western tank battery entrance. Road base material and culvert remain.

Inspection Photos  
Location Name: Callen - USX N-65N67W  
Location ID: 306751



**Photo 5.** Google Earth aerial imagery (circa 11/2024) illustrating that the two tank battery entrances remain and will require additional reclamation activities. Meter sheds pictured have been removed at the time of this inspection.