

# Inspection Photos

API: 017-06678

Operator: **DECLAR OIL & GAS INC**

Inspection Date: 1/28/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north toward the access road. There are areas of the road that have not established vegetation and there are undesirable weeds.



## Inspection Photos



**Photo 2.** Facing north toward the location which has a fence around the perimeter.



## Inspection Photos



**Photo 3.** Facing north toward the location. The location is mostly bare of vegetation and appears to have impacted soils from a historic spill.



## Inspection Photos



**Photo 4.** East side of the location facing west. There is no vegetation growth at the location which is approximately 250'x250'.



## Inspection Photos



**Photo 5.** There is a black hardened hydrocarbon material at the east side of the location shown in this photo.



## Inspection Photos



**Photo 6.** North side of the location facing south. There is no vegetation growth at the location which is approximately 250'x250'.



Inspection Photos



**Photo 7.** Facing south at the location. Remnants of debris remain.



## Inspection Photos



**Photo 8.** Facing west at the location. It appears there are downhill flow pattern where vegetation is not growing. This is indicative of a historic spill causing a salt kill of vegetation..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06678 | Date: 1/28/2025

Inspection Photos



**Photo 9.** Facing north at the location.



## Inspection Photos



**Photo 10.** Facing east toward the surrounding undisturbed reference which consists of Blue grama, Threeawn, Sand dropseed among other native plant species.

