

# Inspection Photos

January 24th, 2024

Operator: Abundance Energy - 10840

Location ID: 322792

Inspection Document #: 714001763

La Plata County, CO

Township: SENW 27 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Jacques  
Location ID: 333792



**Photo 1.** View of the well pad from the access point facing center. Note: location/well signs not displaying current operator.



Inspection Photos  
Location Name: Jacques  
Location ID: 333792



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Eastern interim reclamation area composed of Sand Dropseed, Four Winged Saltbush and Sand Dropseed.

API #: Multi Well Pad



Inspection Photos  
Location Name: Jacques  
Location ID: 333792



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Cellar at well head (#1) is missing wildlife covering/netting.

API #: Multi Well Pad



Inspection Photos  
Location Name: Jacques  
Location ID: 333792

1/24/25  
132° SE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area composed of Sand Dropseed, Juniper, Gamble Oak and Rabbitbrush.

API #: Multi Well Pad