

Inspection Photos
Location Name: Sheldon Sickler 1
Location ID: 317661



Photo 1 Location



Photo 2 Tall dead vegetation around the Wellhead.

Inspection Photos
Location Name: Sheldon Sickler 1
Location ID: 317661



Photo 3 Tall dead vegetation around the Wellhead sign.



Photo 4 Tall dead vegetation around the Ancillary equipment.

Inspection Photos
Location Name: Sheldon Sickler 1
Location ID: 317661



Photo 5 Dead vegetation around the ROW & equipment.



Photo 6 Dead vegetation around the ROW & equipment.

Inspection Photos
Location Name: Sheldon Sickler 1
Location ID: 317661



Photo 7 Dead vegetation around the ancillary equipment.



Photo 8 Dead vegetation around the equipment.