

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 1 Location



Photo 2 Wellhead.

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 3 Tall dead vegetation around the Wellhead sign.



Photo 4 Ancillary equipment.

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 5 Dead vegetation around the ROW & equipment.



Photo 6 Dead vegetation around the ROW & equipment, belt cover lying on the ground.

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 7 Dead vegetation around the ancillary equipment.



Photo 8 Dead vegetation around the equipment.

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 9 Dead vegetation around the tank battery.



Photo 10 Dead vegetation around the Tank battery.

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 11 Dead vegetation around the tank battery sign.



Photo 12 Dead vegetation around the Horizontal heated separator.

Inspection Photos
Location Name: Sheldon Sickler 2
Location ID: 317693



Photo 13 Dead vegetation around the Horizontal heated separator.




Photo 14 Dead vegetation around the flow line manifold