

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28NESW

Location ID: 324130

Date: 1/28/2025



Location – Photo #06255



Location – Photo #06243

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28NESW

Location ID: 324130

Date: 1/28/2025



Location – Photo #06253



Location – Photo #06254



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28NESW

Location ID: 324130

Date: 1/28/2025



**Stained Soil/Leak – Photo #06244**



**Stored Supplies/Wildlife Entry Hazard – Photo #06247**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/28NESW

Location ID: 324130

Date: 1/28/2025



Stored Supplies/Wildlife Entry Hazard – Photo #06248



Stored Supplies/Wildlife Entry Hazard – Photo #06246