

## Inspection Photos

Operator: KINDER MORGAN CO2 CO LLC – 46685

Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 1/29/2025 Inspection Doc#: 693807980



01.29.2025 13:56

Location overview looking N



01.29.2025 14:00

Injection wellhead housing  
Secondary containment of chemicals

## Inspection Photos

**Operator: KINDER MORGAN CO2 CO LLC – 46685**

**Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1**

**Location ID: 313469    API #: 05-083-06195**

**Inspection Date: 1/29/2025    Inspection Doc#: 693807980**



**Tank Battery**



**Manifold Housing and control station**

# Inspection Photos

Operator: KINDER MORGAN CO2 CO LLC – 46685

Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 1/29/2025 Inspection Doc#: 693807980



Offload station



Sensor readout panel