

# Inspection Photos

API: 017-06379

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 1/28/2025

County: Cheyenne




## Inspection Photos



**Photo 1.** Facing along the access road. The soil pushed off of the road into pile will need to be regraded.



## Inspection Photos




**Photo 2.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 3.** There is orange safety fence use to cover the containment. Well sign has been updated.



## Inspection Photos



**Photo 4.** There is oil stained soils around the flowline and equipment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 5.** There are stained soils that appear to have been shoveled out onto the road. All spill oily waste must be cleaned up and properly disposed.



## Inspection Photos



**Photo 6.** View of oily waste on the road way shown in the previous photo.

