

Inspection Photos
Location Name: DF Ranch 8-15
Location ID: 310707



Photo 1 – Sign at Lease Road Entrance



Photo 2 – Pumping Unit

Inspection Photos
Location Name: DF Ranch 8-15
Location ID: 310707



Photo 3 – Well Sign does not reflect current Operator



Photo 4 – Pumping Unit