

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3467 Entrance to location



Photo # 3478 Location

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3468 Location



Photo # 3472 Location

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3476 Location



Photo # 3477 Location

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3515 NE corner of location



Photo # 3516 NW corner of location

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3517 SW corner of location



Photo # 3518 SE corner of location

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3496 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3497 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos
Location: QB Energy Mesa/N23-697 Pad
Location ID: 448427
Date: 01/27/2025



Photo # 3498 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 3499 PRV vent line does not comply with CECMC pressure safety device rules