

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 01/28/2025



Photo # 3693 Entrance to location



Photo # 3700 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 01/28/2025



Photo # 3694 Location



Photo # 3696 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 01/28/2025



Photo # 3699 Location



Photo # 3708 NW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 01/28/2025



Photo # 3709 SW corner of location



Photo # 3710 SE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 01/28/2025



Photo # 3711 NE corner of location



Photo # 3704 Suspected leaks on production tank/tank appears to lack integrity

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Wagon Track Federal/12-16 Pad

Location ID: 312657

Date: 01/28/2025



Photo # 3706 Suspected leaks on production tank/tank appears to lack integrity



Photo # 3707 Suspected leaks on production tank/tank appears to lack integrity