

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3655 Entrance to location




Photo # 3663 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3656 Location



Photo # 3658 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Jan 28, 2025 at 12:24:52 PM
+39.285920,-108.254300 ±3.94m
De Beque

Photo # 3662 Location



Jan 28, 2025 at 12:45:21 PM
+39.285821,-108.254478 ±5.89m
De Beque

Photo # 3672 SW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3673 SE corner of location



Photo # 3674 NE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3675 NW corner of location



Photo # 3676 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3678 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment



Photo # 3680 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3683 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment



Photo # 3684 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3686 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment



Photo # 3687 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Ed Koch/7-9 Pad

Location ID: 312638

Date: 01/28/2025



Photo # 3689 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & transport of sediment



Photo # 3669 Tank has a large amount of rust. All in service tanks will be inspected & maintained