

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 01/28/2025



Photo # 3602 Entrance to location



Photo # 3608 Location

Inspection/Audit Photos
Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad
Location ID: 312652
Date: 01/28/2025



Photo # 3603 Location



Photo # 3604 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 01/28/2025



Photo # 3607 Location



Photo # 3610 Tank is empty and locked/tagged out, hole is still in tank and lacks integrity

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 01/28/2025



Photo # 3615 NW corner of location



Photo # 3616 SW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Castle Rock/18-4 Pad

Location ID: 312652

Date: 01/28/2025



Photo # 3617 SE corner of location



Photo # 3618 NE corner of location