

Inspection Photos

01/29/2025

Operator: LONE MOUNTAIN PRODUCTION
COMPANY - 51090

Location ID: 312348

Inspection Doc: 718100233

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 1: Photos taken from the north end of the Location; based on historic aerial imagery, the well was located within areas of the current compressor station; the remaining production facilities were located within the areas of these photos. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 3: Photos taken from the adjacent reference areas for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LONE MOUNTAIN PRODUCTION COMPANY - 51090

Location ID: 312348



Photo 4: Riser equipment remaining on the south end of the Location. pursuant to Rule 1004.a, all abandoned gathering line risers, flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources