

# Inspection Photos

01/29/2025

**Operator:** NORTHSTAR RESOURCES, INC

**Location ID:** 312411

**Inspection Doc:** 718100235

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: NORTHSTAR RESOURCES, INC

Location ID: 312411



**Photo 1:** Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: NORTHSTAR RESOURCES, INC  
Location ID: 312411



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: NORTHSTAR RESOURCES, INC  
Location ID: 312411



**Photo 3:** Separator equipment remaining on the west end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources