

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MONUMENT RIDGE B PAD

Location ID: 442832

Date: 1/29/2025



Location Overview – Photo #06273



Location – Photo #06274

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MONUMENT RIDGE B PAD

Location ID: 442832

Date: 1/29/2025



Location – Photo #06285



Location – Photo #06283

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MONUMENT RIDGE B PAD

Location ID: 442832

Date: 1/29/2025



Location – Photo #06275



Location – Photo #06282

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MONUMENT RIDGE B PAD

Location ID: 442832

Date: 1/29/2025



Location – Photo #06288

Wildlife Entry Hazard – Photo #06286

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MONUMENT RIDGE B PAD

Location ID: 442832

Date: 1/29/2025



Jan 29, 2025 at 13:03:52
Parachute CO 81635
United States



Jan 29, 2025 at 13:05:20
Parachute CO 81635
United States

Wildlife Entry Hazard – Photo #06287

Wildlife Entry Hazard – Photo #06290

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MONUMENT RIDGE B PAD

Location ID: 442832

Date: 1/29/2025



Jan 29, 2025 at 13:05:33
Parachute CO 81635
United States



Jan 29, 2025 at 13:07:24
Parachute CO 81635
United States

Wildlife Entry Hazard – Photo #06291

Location – Photo #06292