

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 1/30/2025



Location Overview – Photo #06365



Location – Photo #06362



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 1/30/2025



Location – Photo #06367



Location – Photo #06368



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 1/30/2025



Location – Photo #06369



Location – Photo #06370



## Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 1/30/2025



Location – Photo #06366



Illegible Wellhead Sign – Photo #06363



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 1/30/2025



Illegible Wellhead Sign – Photo #06364



Open-Ended Load Line – Photo #06371