

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 1/30/2025



Location Overview – Photo #06373



Location – Photo #06375

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 1/30/2025



Location – Photo #06381



Location – Photo #06377

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 1/30/2025



Open Wellhead Cellar – Photo #06374



Trash – Photo #06383

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 1/30/2025



Open-Ended Load Line – Photo #06378



Lack of Stabilization – Photo #06379

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWNE

Location ID: 335459

Date: 1/30/2025



Insufficient Tracking BMPs – Photo #06384