

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 1/30/2025



Location Overview – Photo #06386



Location – Photo #06387

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 1/30/2025



Location – Photo #06389



Location – Photo #06388

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 1/30/2025



Location – Photo #06391



Open-Ended Load Line – Photo #06390

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 29-27

Location ID: 323789

Date: 1/30/2025



Lack of Stabilization – Photo #06392



Insufficient Tracking BMPs – Photo #06393