

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404059273

Date Received:

01/17/2025

Spill report taken by:

Rollins, Grace

Spill/Release Point ID:

489220**SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)**

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 515-0055</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>()</u>
Zip: <u>80217-3779</u>		Email: <u>DJRemediation_Forms@oxy.com</u>
Contact Person: <u>Jaron Bartoszek</u>		

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORTInitial Spill/Release Report Doc# 404059273

Initial Report Date: 01/15/2025 Date of Discovery: 01/15/2025 Spill Type: Historical Release

Spill/Release Point Location:QTRQTR SENE SEC 5 TWP 3N RNG 66W MERIDIAN 6Latitude: 40.256928 Longitude: -104.795911Municipality (if within municipal boundaries): _____ County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☐ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:Facility Type: WELL SITE☐ Facility/Location ID No _____Spill/Release Point Name: Champlin 203 AM A 1 Wellhead☒ Well API No. (Only if the reference facility is well) 05-123-14601☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): UnknownEstimated Condensate Spill Volume(bbl): UnknownEstimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use:	CROP LAND	Other(Specify):	
Weather Condition:	Partly Cloudy 18°F		
Surface Owner:	FEE	Other(Specify):	

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

While conducting wellhead plugging and abandonment and flowline removal activities at the Champlin 203 AM A 1 wellhead, historically impacted soil and groundwater were discovered at the wellhead. The volume of the release is unknown. Assessment activities are ongoing. The assessment details will be summarized in a supplemental Form 27 report (Remediation No. 36286; Form 27 Initial Document No. 403841643). The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
1/15/2025	CO Parks & Wildlife	CO Parks & Wildlife	-	Notified via email
1/15/2025	Surface Owner	Surface Owner	-	Notified via phone
1/15/2025	Weld County	Weld County	-	Notified via email

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

- Yes Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: Threatened to Impact Public Water System: n/a
- Residence or Occupied Structure: n/a Livestock: n/a
- Wildlife: n/a Publicly-Maintained Road: n/a
- No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery _____ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
- Enter the Document Number of the Initial Accident Report, Form 22 _____
- Was there damage during excavation? _____
- Was CO 811 notified prior to excavation? _____
- Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): 10
- Yes Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☒ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/17/2025		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL			<input checked="" type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☒ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): _____ Width of Impact (feet): _____

Depth of Impact (feet BGS): _____ Depth of Impact (inches BGS): _____

How was extent determined? _____

Assessment and remediation activities are being conducted under Table 915-1 standards and the historically impacted soil will be removed. The analytical results and assessment details will be provided in a supplemental Form 27 report (Remediation No. 36286; Form 27 Initial Document No. 403841643). A photo log is included as an attachment.

Soil/Geology Description:

Well-Graded Sand (SW)

Depth to Groundwater (feet BGS) 6 Number Water Wells within 1/2 mile radius: 27

If less than 1 mile, distance in feet to nearest	Water Well	<u>670</u>	None <input type="checkbox"/>	Surface Water	<u>210</u>	None <input type="checkbox"/>
	Wetlands	<u>445</u>	None <input type="checkbox"/>	Springs		None <input checked="" type="checkbox"/>
	Livestock	<u>1170</u>	None <input type="checkbox"/>	Occupied Building	<u>950</u>	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 01/17/2025

Root Cause of Spill/Release Unknown (Historical)

Other (specify)

Type of Equipment at Point of Spill/Release: Wellhead Line

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

While conducting wellhead plugging and abandonment and flowline removal activities at the Champlin 203 AM A 1 wellhead, historically impacted soil and groundwater were discovered at the wellhead. The volume of the release is unknown. Assessment activities are ongoing.

Describe measures taken to prevent the problem(s) from reoccurring:

The wellhead has been plugged and abandoned.

Volume of Soil Excavated (cubic yards):

Disposition of Excavated Soil (attach documentation) ☐ Offsite Disposal ☐ Onsite Treatment ☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls):

Volume of Impacted Surface Water Removed (bbls):

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

- Basis for Closure:
- ☐ Corrective Actions Completed (documentation attached, check all that apply)
 - ☐ Horizontal and Vertical extents of impacts have been delineated.
 - ☐ Documentation of compliance with Table 915-1 is attached.
 - ☐ All E&P Waste has been properly treated or disposed.
 - ☒ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: 36286
 - ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Jaron Bartoszek

Title: Environmental Advisor Date: 01/17/2025 Email: DJRemediation_Forms@oxy.com

COA Type**Description**

	Quarterly reporting (90 days) is required under Remediation Project # 36286. Operator shall include the Spill ID associated with this form on the subsequent Supplemental Form 27 and select Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912 in addition to the previous Rule selection.
1 COA	

ATTACHMENT LIST**Att Doc Num****Name**

404059273	SPILL/RELEASE REPORT(I/S)
404060325	TOPOGRAPHIC MAP
404060326	CORRESPONDENCE
404060395	PHOTO DOCUMENTATION
404081939	FORM 19 SUBMITTED

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

Environmental	ECMC updated the sensitive receptor distances to include the following: -The nearest wetlands (Freshwater Emergent) is 445 ft from the location, as mapped on the National Wetland Inventory Maps	02/05/2025
---------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------

Total: 1 comment(s)