

# Final Reclamation and Stormwater Inspection

Date: 01/31/2025

Operator: HOUSTON EXPLORATION COMPANY\* THE  
- 10068

Location ID: 411450

Inspection Document #: 718700036

Yuma County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 1.** Taken near the start of the access road. Portions of the access road do not appear to be progressing towards Rule 1004 standards and regulation with evidence of bare soils.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 2.** Taken along the access road. Portions of the access road do not appear to be progressing towards Rule 1004 standards and regulation with evidence of bare soils.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 3.** Taken along the access road. Portions of the access road do not appear to be progressing towards Rule 1004 standards and regulation with evidence of bare soils.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 4.** Taken along the access road. Portions of the access road do not appear to be progressing towards Rule 1004 standards and regulation with evidence of bare soils.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 5.** Taken along the access road. Red dotted line illustrates that the access road does not appear to have been recontoured to reflect adjacent topography.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 6.** Taken from the southern end of the former well location. Portions of the the reclaimed well location appear to be progressing towards reclamation standards with evidence of desirable vegetation.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 7.** Western portions of the former well location do not appear to be progressing towards reclamation standards with areas of non-uniform vegetation cover.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 8.** Taken from the northern end of the former well location. Portions of the the reclaimed well location appear to be progressing towards reclamation standards with evidence of desirable vegetation.



Inspection Photos  
Location Name: Bledsoe 3-5-3-43  
Location ID: 411450



**Photo 9.** Eastern portions of the former well location do not appear to be progressing towards reclamation standards with areas of non-uniform vegetation cover.